CERTIFICATE OF COMPLIANCE

Certificate Number	R38679
Report Reference	R38679- 20181127
Issue Date	2023-May-15

Issued to: Coopers Fire Ltd

Ignis House, Houghton Ave
Hants
Waterlooville, PO7 3DU United Kingdom

This is to certify that representative samples of FIRE-PROTECTIVE CURTAINS

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: ANSI/UL 10D - Standard for Fire Tests of Fire-Protective Curtain Assemblies

Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.

Bruce Mahrenholz, Director North American Certification Program

UL LLC

CERTIFICATE OF COMPLIANCE

Certificate Number R38679
Report Reference R38679- 20181127
Issue Date 2023-May-15

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Fire-protective curtain, Model FireMaster Egress, 3 hr fire rating when installed into gypsum/plaster board walls), 4 hr when installed into masonry walls.

Fire-protective curtain, Model FireMaster Non-Egress, 3 hr fire rating when installed into gypsum/plaster board walls), 4 hr when installed into masonry walls..

Bruce Mahrenholz, Director North American Certification Program

UL LLC