

CERTIFICATE OF COMPLIANCE

Certificate Number 20190404-R38679
Report Reference R38679-20181127
Issue Date 2019-APRIL-04

Issued to: Coopers Fire Ltd
Edward House
Penner Road
Havant
PO9 1QZ UNITED KINGDOM

**This certificate confirms that
representative samples of**

FIRE-PROTECTIVE CURTAINS

FireMaster Egress and FireMaster Non-Egress, rated up to and including 3 hr. for use in gypsum wall and 4 hr for use in masonry wall type constructions.

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.


Standard(s) for Safety:
Additional Information:

UL 10D, Fire Tests of Fire-Protective Curtain Assemblies
See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

