

CERTIFICATE OF COMPLIANCE

Certificate Number R38679
Report Reference R38679- 20180625
Issue Date 2023-May-15

Issued to: Coopers Fire Ltd
Ignis House, Houghton Ave
Hants
Waterlooville, PO7 3DU United Kingdom

This is to certify that representative samples of FIRE-PROTECTIVE CURTAINS

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: ANSI/UL 10D - Standard for Fire Tests of Fire-Protective Curtain Assemblies

Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number R38679
Report Reference R38679- 20180625
Issue Date 2023-May-15

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Fire-protective curtain, Model FireMaster Concertina, 4 hr fire rating.

Fire-protective curtain, Model FireMaster Concertina Egress, 2 hr fire rating.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

