

CERTIFICATE OF COMPLIANCE

Certificate Number 20180626-R38679
Report Reference R38679-20180625
Issue Date 2018-JUNE-26

Issued to: Coopers Fire Ltd
Edward House
Penner Road
Havant
PO9 1QZ UNITED KINGDOM

This is to certify that representative samples of FIRE-PROTECTIVE CURTAINS
FireMaster Concertina, rated up to and including 4 hr., for use in gypsum or masonry wall type constructions.

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: ANSI/UL 10D, Fire Tests of Fire-Protective Curtain Assemblies

Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

